

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPMC Abayi axis
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 11/06/12 ii. Date first reported: 13/06/12
 - iii. Date of first investigation: 15-June 2012
 - iv. Date of follow-up investigation:
 - v. Time investigation started: 11:59 am
 - vi. Estimated quantity spilled: Heavy
4. Site Details
 - i. Site Location: Km 45 Chukara, Abayi axis
 - ii. Position of Spill Leak: N 08° 24.195' E 006° 56.512'
 - iii. Spill area
 - ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
 - ☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause Of Spill
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

☒ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

☒ Within Company's facility ROW ☐ Outside Company's facility ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i.

i.

ii.

ii.

iii.

iii.

iv.

iv.

c) Creeks/Creeklets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken..... Soil

10. Investigation carried out by



☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... The impacted site must be cleaned up and remediated immediately under the supervision of the agency.

12. Time investigation ended..... 12:45 pm

13. Name and Signature of Participants

❖ NOSDRA

1. Alexander D. Mutshon 
2. Boon Musa 
- 3.

❖ DPR

- 1.
- 2.
- 3.


❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY PPMC KADUNA AREA OFFICE

1. Belu Jasper M 
- 2.
- 3.

❖ COMMUNITY

- 1.
- 2.
- 3.