



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: PPMC/NNPC
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details  
i. Date of Incident: 11/06/13    ii. Date first reported: 11/06/13  
iii. Date of first investigation: 12/06/13  
iv. Date of follow-up investigation:.....  
v. Time investigation started: 10:46am  
vi. Estimated quantity spilled: Minor
4. Site Details  
i. Site/Location: Km 265 (Crude Line Mark) Gazamari  
ii. Position of Spill/Leak: N 10° 29' 27" E 007° 32' 22"  
iii. Spill area  
☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....  
iv. Structural Controls in Place  
☐ Boom    ☐ Trenches    ☐ Bund wall    ☐ Sorbents    ☐ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☐ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock  
ii. Type of Oil contaminant  
☐ Crude Oil    ☐ Condensate    ☐ Chemicals    ☒ Refined Products  
☐ Others (specify) .....
- iii. Facility  
☒ Pipeline    ☐ Flow line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify).....
- iv. Cause Of Spill  
☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify).....
- v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☒ Theft    ☐ Acid  
☐ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

b) Land (indicate area in  $m^2$ )

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken..... No

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... Effect the Repair of the  
Vandalized port and improve on  
Security Surveillance.

12. Time investigation ended..... 12-18pm.

13. Name and Signature of Participants

❖ NOSDRA

1. Anthony Chikwura Agunwa. [Signature] 12/06/13
2. Gwabza Daniel -A. [Signature] 12/06/13
3. Aminu Abbas [Signature] 12/06/13

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. BELLO J.M [Signature] 12/06/2013
2. / / / /
3. / / / /

❖ COMMUNITY

- 1.
- 2.
- 3.