



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		024 / 2023	
Section 2 - Location			
State / LGA		Ubit PP OML 67 - / Akwa Ibom	
Coordinates of spill		EASTINGS 4Deg 16Min/28Secs N NORTHINGS 9Deg 10Min/33Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		12/20/2023 Time: 06:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☒ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Other (Process Upset): Multiple gas leaks from three vulnerable lines on Ubit GY platform due to back pressure during EAP emergency shut down, led to some hydrocarbon liquid drop into the sea, resulting in silvery surface. Sheen dispersed naturally.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): ESD activated, and leak stop	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Sulphur Content		

	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat
☐ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release			
		Per Hour		☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00013bbl of crude oil based on sheen appearance.			
	Coverage	About 40% light brown and 60% silvery sheen on sea water			
	Direction of travel	South West			

Section 5 - Weather

METEOROLOGICAL DATA

Wind Direction (wind direction given from)	North East
Initial Wind Speed	2knots
Air Temperature (C or OF)	32°C
Visibility Estimate	☒ Good ☐ Fair ☐ Poor

Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☐	No ☐

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

