

FID: 1771837



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify) WATER LEAK

3. Incident Details

i. Date of Incident: 13/02/2024 ii. Date first reported: 13/02/2024

iii. Date of first investigation: 16/02/2024

iv. Date of follow-up investigation:

v. Time investigation started: 14:10 HRS

vi. Estimated quantity spilled: NIL

4. Site Details

i. Site/Location: 8th ASSA Runmekpe P/LAT. MOGU Community / Runmekpe

ii. Position of Spill/Leak: N05° 03' 17.4112 E 006° 70' 11.659

iii. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (Specify) WATER LEAK

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) NIL

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock

☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (Specify) WATER LEAK

iii. Facility

☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

☐ Others (Specify)

2" Nipple cased on the Line for oil theft activities by unknown person or persons

Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify) ... NIL

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify) ... NIL

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i. IMOGU Community
 ii. RUMU EKPE
 iii. _____
 iv. _____

(b) Land (Indicate area in m²)

- i. NIL
 ii. _____
 iii. _____
 iv. _____

(c) Creek/Creek lets

- ☐ Tidal
 ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal
 ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal
 ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal
 ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☐ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation... SPDC should remove the illegal connection on the pipe line, And Repair the affected pipe.

12. Time Investigation ended... 14:55 HRS