

005/2024

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY (NOSDRA)



ATTENDANCE

S/N.	NAME	ORGANISATION	SIGN	E-MAIL	PHONE NO.
1	OMOYA A BRIGHT	NOSDRA		Brightomoya@gmail.com	0812817617
2	ITIOLA OLUWATOYIN	OMD State Energy		Itiola.succes@gmail.com	08262659367
3	Genesis Gbemo	Opuama			08059156172
4	KINALEY EJEH	CNL		lgesc2281@chevron.ca	09125093679
5	ABOH GADIRI FRANCIS	OPUDS PIA		gifelism@gmail.com	08050706271
6	OMOSUYI SIMON	ILAGE PIA		omosuyi.simon131@gmail.com	0805181060
7	OMOMULERE AJESUNFA	ILAGE PIA			08164564564
8	DIRI ALFRED	CITENOW NIG LTD		Sdir@chevron.com	08025889646
9	Ofor LUCE	Chevron Nig. Ltd		ofor@chevron.com	08025889628
10					
11					
12					
13					
14					
15					
16					
17					
18					



005/2024

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: CHEURON NIGERIA LIMITED

2. Type of Complaint/Incident:

☐ Oil Pollution

☐ Fire/Explosion

☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) OTB

3. Incident Details

i. Date of Incident: 31/01/2024

ii. Date first reported: 01-02-2024

iii. Date of first investigation: 13-02-2024

iv. Date of follow-up investigation: —

v. Time investigation started: —

vi. Estimated quantity spilled: NON

4. Site Details

i. Site/Location: OPUEKEBA Well 10. 4" PIPELINE

ii. Position of Spill Leak: —

iii. Spill area

☐ Land

☒ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near Shore

☐ Offshore

☐ Others (Specify) NON

IV. Structural Controls in Place

☐ Boom

☐ Trenches

☐ Bund Wall

☐ Sorbent

☐ Others (Specify) NON

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock

☐ 10 O' Clock

☐ 2 O' Clock

☐ 3 O' Clock

☐ 4 O' Clock

☐ 5 O' Clock

☐ 6 O' Clock

ii. Type of Oil containment

☐ Crude Oil

☐ Condensate

☐ Chemical

☐ Refined Product

☐ Other (Specify) NON

iii. Facility

☐ Pipeline

☒ Flow line

☐ wellhead

☐ Manifold

☐ Flow station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify) —

iv. Cause Of Spill

☐ Corrosion

☐ Equipment Failure

☐ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify) NO SPILL

v. Visible Sign of Third Party Interference

☐ Hacksaw Mark

☐ Drilled Holes

☐ Blasting

☐ Theft

☐ Acid

☐ Others (Specify) Yes, Welded Valve

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) ... NOT APPLICABLE

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal * ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation.....

12. Time investigation ended..... 14:00 hrs