



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY  
JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company:

*See This JIV form is to be completed and signed by all participating parties in the field*  
**HICKS ENTERPRISES**

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify):

3. Incident Details:

i. Date of Incident:

**12/02/2024**

ii. Date first reported:

**12/02/2024**

iii. Date of first investigation:

**12/02/2024**

iv. Date of follow-up investigation:

**12/29/2024**

v. Time investigation started:

**10:45 AM**

vi. Estimated quantity spilled:

**26196 MGA of fluid at Umuvalia**

4. Site Details:

i. Site location:

**0070 CA 11 IE, 04° 53' 26" N**

ii. Position of Spill/Leak:

iii. Spill area:

- ☒ RT and    ☐ Seepage    ☐ Freshwater    ☐ Mangrove    ☐ Coastal  
☐ Near shore    ☐ Offshore    ☐ Others (Specify):

iv. Structural Controls in Place:

**HIA**

- ☐ Buoys    ☐ Trenches    ☐ Bund Wall    ☐ Berthment    ☐ Others (Specify):

5. Circumstances Around Spill Point:

i. Visual observation of Hole Position:

- ☐ 12:00 Clock    ☐ 10:00 Clock    ☒ 2:00 Clock    ☐ 3:00 Clock  
☐ 4:00 Clock    ☐ 5:00 Clock    ☐ 6:00 Clock

ii. Type of Oil Contaminant:

- ☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (Specify):

iii. Facility:

- ☐ Pipeline    ☒ Flow Line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant  
☐ Others (Specify):

iv. Cause of Spill:

- ☒ Corrosion    ☐ Equipment Failure    ☐ Third Party Interference    ☐ Accidents  
☐ Operational Error    ☐ Others (Specify):

v. Visible Signs of Third Party Interference:

- ☐ Hack saw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Arson  
☒ Others (Specify): **A pin hole caused by corrosion**

# 6. Impact of Incident

## i. Properties Impacted by the Incident

4/1A

- ☐ Fertilized ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable (Objects) ☐ Others (Specify)

## ii. Nature of impact

4/1A

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
 Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

## iii. Delimitation of Impacted area

☒ Within Company's facility/ROW

☐ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

### (b) Land (Indicate area in m<sup>2</sup>)



### (c) Creek/Creek bed

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLACK | LENGTH OF SLACK | WIDTH OF SLACK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLACK | LENGTH OF SLACK | WIDTH OF SLACK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLACK | LENGTH OF SLACK | WIDTH OF SLACK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLACK | LENGTH OF SLACK | WIDTH OF SLACK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photographs taken? ☒ None

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken

N/A

10. Investigation carried out by

☒ None

☐ Boat

☐ Aircraft

11. Remarks/Recommendation

The ship should be selected for  
and search of logs in the vicinity of  
be carried out within 5 days

12. Time investigation ended