



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		0817 207 3919	
Email Address		Mark.w.fraser@exxonmobil.com	
Incident Number		005 / 2024	
Section 2 - Location			
State / LGA		Edop PP OML 67 - /	
Coordinates of spill		EASTINGS 4Deg 8Min/9Secs N NORTHINGS 7Deg 58Min/4Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		2/25/2024 Time: 08:30 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Leak was from failed instrument fitting on wellhead test separator.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Test separator shut-in, isolated and depressurized. Leak stopped and instrument team completed scoping for replacement of leaking fitting.	
Product Data	☐ Persistent		☒ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		

Oil	Slick Locations(s)		
-----	--------------------	--	--

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00019bbls of crude oil based on sheen appearance	
	Coverage	About 200m X 10m 80% water, 10% discernible and 10% silvery sheen on sea water	
	Direction of travel	North	
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)	North		
Initial Wind Speed	6knots		
Air Temperature (C or OF)	29°C		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐	Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☒	
Recovery of free phase oil	Yes ☐	No ☒	
Booming	Yes ☐	No ☒	
Wild life rehabilitation	Yes ☐	No ☒	
Dispersant application	Yes ☐	No ☒	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

