



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark W. Fraser	
Designation		General Manager Joint Venture Operations	
Phone Number		0817 207 3917	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		008/ 2024	
Section 2 - Location			
State / LGA		Akwa Ibom / Ibeno	
Coordinates of spill		EASTINGS 4Deg 8Min/9Secs N NORTHINGS 7Deg 58Min/4Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		4/17/2024 Time: 14:46 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☒ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Corrosion: During plant walkthrough, oily water was found dripping into the sea from a corroded point between a 3" line from the open drain of the crude oil slop tank and the open drain header.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify)...Oily water drip stopped and was mitigated by flushing skid with detergent,	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type	NA	NA
	SG/API Gravity	NA	NA
	Pour Point	NA	NA
	Wax Content	NA	NA
	Sulphur Content	NA	NA

	Viscosity	NA	NA
Oil	Slick Locations(s)	NA	NA

observation	Slick Dimension(s)	NA	NA
	Orientation of slick(s)	NA	NA
	Distribution of oil	NA	NA
	Obvious odour	NA	NA
Oil descriptions	Tarballs (tb)	NA	NA
	Convergence line (co)	NA	NA
	No structure (ns)	NA	NA
	Windrows (wr)	NA	NA
	Streamers (st)	NA	NA
	Patches (pa)	NA	NA
Oil color and appearance	Silver/grey	NA	NA
	Rainbow	NA	NA
	Metallic	NA	NA
	Transitional	NA	NA
	Dark	NA	NA

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat
☒ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release			
		Per Hour		☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00164 bbls of crude oil based on sheen appearance			
	Coverage	About 200m X 12m of 1% light brown, 1% barely discernible, 8% silvery sheen and 90% Clear Sea water			
	Direction of travel				

Section 5 - Weather

METEOROLOGICAL DATA

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	Northeast	
Initial Wind Speed	6 knots	
Air Temperature (C or OF)	26 degrees Celsius	
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	

Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)	26 degrees Celsius	
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☐	No ☐

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

