



2024/NEOL/ALAK/006

# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

## JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NNPCL

### 2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

### 3. Incident Details

- i. Date of Incident: 13:03:2024 ii. Date first reported: .....  
iii. Date of first investigation: 15:03:2024  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 1300 HRS  
vi. Estimated quantity spilled: 4 bbls

### 4. Site Details

- i. Site/Location: WELL 34T ALAKURI AT OKINKA LGA R/STATE  
ii. Position of Spill/Leak: N 04° 38' 40.6" E 007° 03' 33.9"  
iii. Spill area  
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☒ Near shore ☐ Offshore ☐ Others (Specify) .....  
iv. Structural Controls in Place  
☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) .....

### 5. Circumstances Around Spill Point

#### i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock  
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

#### ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (Specify) .....

#### iii. Facility

- ☐ Pipeline ☐ Flow Line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify) .....

#### iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (Specify) .....

#### v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid  
☒ Others (Specify) FIRE

## 6. Impact of Incident

### i. Properties Impacted by the Incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☒ Surface water  
☐ Venerable Objects   ☐ Others (Specify) .....

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
 Dead floating crabs   Withering of vegetation   Others (Specify) .....

### iii. Delimitation of Impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

### (b) Land (Indicate area in m<sup>2</sup>)

- i. KIRIYO .....  
 ii. OFONIMANA .....  
 iii. ....  
 iv. ....

### (c) Creek/Creeklets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

3. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☐ Foot    ☒ Boat    ☐ Aircraft

11. Remarks/Recommendations

Clean-up and Recovery should be carried out immediately. we however commend the Surveillance team for prompt action and advise on more proactive measures to prevent re-occurrence.

12. Time Investigation ended

1500 HRS