



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 - Site Organization		Mandatory Information Required	
Company Name	FPSO PRINCESS AWENI		
Reporting Officer	Gidigbi Ayodiran		
Designation	OIM		
Phone Number	09065994892		
Email Address	ayodiran.gidigbi@amni.com		
Incident Number			
Section 2 - Location			
State/ LGA	AKWA IBOM/EASTERN OBOLO		
Coordinates of spill	04deg 24.3' N 007deg 49.7' E		
	☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others		
Depth of Water (if applicable)			
Section 3 - Spill Details			
Date and Time of spill	DD : MM : YYYY	16th April 2024 1430hrs	
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker/Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter12inh.) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Delivery line ☒ Exportline ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flowstation ☒ Rig ☐ Compressor Plant ☒ FPSO ☐ Refinery ☐ Others.....		
Cause of spill	Hose damage still under investigation		
Status of spill	☒ Contained ☐ Not Contained ☐ Unknown		
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☒ Sorbent ☐ Others (specify).....		
Product Data	☐ Persistent		☒ Non Persistent
	Product Name/Type	Okoro Crude	
	SG/API Gravity	33.5	
	Pour Point	+5	
	Wax Content	Nil	
	Asphaltene	Nil	
	Sulphur Content	0.1	
	Viscosity		

Oil observation	Slick location(s)	EXPORT HOSE FLANGE		
	Slick Dimension(s)	5m2		
	Orientation of slick(s)	North West		
	Distribution of oil	Patches		
	Obvious odour	None		
Oil descriptions	Tarballs (tb)			
	Convergence line (co)			
	No structure (ns)			
	Windrows (wr)			
	Streamers (st)			
	Patches (pa)	Yes		
Oil color and appearance	Silver/grey			
	Rainbow	Yes		
	Metallic			
	Transitional			
	Dark			
	Mousse			
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☒ Boat ☐ On site ☐ Others.....		
Section 4 - Approximate Duration				
Release Rate	Instantaneous Release		Continuous Release	
	N/A		Per hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	0.31449bbl		
	Coverage	N/A		
	Direction of travel	NW		
Section 5 - Weather				
METEOROLOGICAL DATA				NIMET weather forecast
Wind Direction (wind direction given from)		Light Airs		
Initial Wind Speed		Light Airs		
Air Temperature (°C or °F)				
Visibility Estimate		☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA				
Water Current Speed		Slack Water		
Tide Phase: Flood		High ☐ Ebb ☐		
Water Temperature (°C or °F)		30deg cel.		
High Tide Time				
Source				
Section 6 - Pre-Entry Activities				
Mechanical cleaning		Yes ☒	No ☐	
Recovery of free phase oil		Yes ☐	No ☐	
Booming		Yes ☐	No ☐	
Wild life rehabilitation		Yes ☐	No ☐	
Dispersant application		Yes ☐	No ☐	
Section 7 - Oil Spill Model Request				
Spill Trajectory	Surface 2D	Sub-surface 3D	Not at this time	
	☐	☐	☒	

Modeling?			
Additional information (please use start date and time)			
A minor oil sheen was noticed while shuttle offtake operation was going on. The operation was immediately aborted and the sheen was effectively contained.			

Section 8- Equipment	
On Site	Oil Booms, Absorbent pads, saw dust, Oil Spill Dispersant, Lamor oil spill equipment and others.

REPORTING OFFICER: Gidigbi Ayodiran

DESIGNATION: OIM

SIGNATURE: DATE: 17th April 2024

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*

☒ Indicate your consent to the processing of your personal data by NOSDRA.
Please visit <https://nosdra.gov.ng/privacy-policy/> to view our Privacy Policy.