

# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

## JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED (NADOC)
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) NON-LEAK
3. Incident Details
  - i. Date of Incident: 10 / 03 / 2024
  - ii. Date first reported: 10 / 03 / 2024
  - iii. Date of first investigation: 10 / 03 / 2024
  - iv. Spill Incident No.: 2024/SAR/NL/022
  - v. Date of follow-up investigation:    /    /
  - vi. Time investigation started: 10:47 HRS
  - vii. Estimated quantity spilled(bbls): NL
  - viii. Quantity Recovered: N/A
4. Site Details
  - i. Site/Location: 18" TEBIDABA / BRASS PIPELINE AT LASUKUNGBENE
  - ii. State: BAYELSA
  - iii. L.G.A.: SOUTHERN IJAW
  - iv. Spill Co-Ordinates: N(m) 04° 30' 19.6"  
E(m) 006° 03' 18.1"
  - v. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (specify)
  - iv. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund wall    ☒ Sorbents    ☒ Others (specify) N/A
5. Circumstances Around Spill Point
  - i. Visual observation of Hole Position  
☒ 12 O' Clock    ☒ 10 O' Clock    ☒ 2 O' Clock    ☒ 3 O' Clock  
☒ 4 O' Clock    ☒ 5 O' Clock    ☒ 6 O' Clock
  - ii. Type of Oil contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (specify) NON LEAK
  - iii. Facility  
☒ Pipeline    ☒ Flow line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☐ Rig  
☒ Storage Tank    ☒ Compressor Plant    ☒ Others (specify)
  - iv. Cause of Spill  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (specify)
  - v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (specify)

## 6. Impact of Incident

### i. Properties impacted by the incident

☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
☒ Others (specify) N/A

### ii. Nature of impact

☒ Oil stained vegetation  
☒ Oil stained fishing nets  
☒ Dead floating fishes  
☒ Dead floating crabs  
☒ Withering of vegetation  
☒ Others... N/A

### iii. Delineation of impacted area

☒ Within Company's facility/ROW  
☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops  
☒ Fish Farm/ Pond  
☒ Fishing Net  
☒ Makeshift  
☒ Permanent  
☒ Others N/A

## 8. Extent of Impact

### a) Community (indicate name)

i. LASUKUGBELE  
 ii. \_\_\_\_\_  
 iii. \_\_\_\_\_  
 iv. \_\_\_\_\_

### b) Land (indicate area in m<sup>2</sup>)

i. N/A  
 ii. \_\_\_\_\_  
 iii. \_\_\_\_\_  
 iv. \_\_\_\_\_

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

10. Samples taken.... N/A .....

11. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

12. Remarks/Recommendation.....

NAOC SHOULD INTENSIFY SURVEILLANCE ON HER FACILITY.

13. Time investigation ended.....