



# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

## JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AIR OIL COMPANY

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: 29/01/2024 ii. Date first reported: 29/01/2024

iii. Date of first investigation: 29/01/2024 iv. Spill Incident No: 2024/SOR/028

v. Date of follow-up investigation: NIL

vi. Time investigation started: 9:10 AM

vii. Estimated quantity spilled(bbls): 0.7 BBL viii. Quantity Recovered: MOPPED

4. Site Details

i. Site/Location: 18" PERIDARA/BRAS PL AT MBIRIBA

ii. State: BAJELA iii. L.G.A: SOUTHERN Ijaw

iv. Spill Co-Ordinates: N(m) 04° 28' 28.9"

E(m) 006° 07' 13.4"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☐ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) MOPPED

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify).....

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Iacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify).....



## 6. Impact of Incident

### i. Properties impacted by the incident

- ☒ Farmland 
 ☒ Fish Pond 
 ☐ Vegetation 
 ☒ Fishing Net 
 ☒ Surface water  
☒ Venerable Objects 
 ☒ Others (specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation 
 ☒ Oil stained fishing nets 
 ☒ Dead floating fishes  
☒ Dead floating crabs 
 ☒ Withering of vegetation 
 ☒ Others .....

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW 
 ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops 
 ☒ Fish Farm/ Pond 
 ☒ Fishing Net 
 ☒ Makeshift  
☒ Permanent 
 ☒ Others ... NIA .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. NRIBA  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

- i. 84.214m<sup>2</sup>  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

10. Samples taken

N/A

11. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

12. Remarks/Recommendation

OIL SPILLED MOVED.  
NO CLEAN-UP REQUIRED  
TIV/REPAIRS COMPLETED  
13:52 HRS

13. Time investigation ended