

2024/LAR/NLI/049



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: ..... NADC .....

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .. NON LEAK .....

3. Incident Details

- i. Date of Incident: 06/05/24 ..... ii. Date first reported: 06/05/24 .....  
iii. Date of first investigation: 06/05/24 .....  
iv. Date of follow-up investigation: NIL .....  
v. Time investigation started: 1045 HRS. .....  
vi. Estimated quantity spilled: NON - LEAK .....

4. Site Details

- i. Site/Location: 6<sup>th</sup> Tuomu - OGBA INBRI P/L @ ADIEGBE EIKEREMOR LGA.  
ii. Position of Spill/Leak: NOS<sup>o</sup> 00' 46.8" E ODS<sup>o</sup> 55' 30.9"

iii. Spill area

- ☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (Specify) .. SEASONAL SWAMP .....

iv. Structural Controls in Place

- ☒ Boom    ☒ Trenches    ☒ Bund Wall    ☒ Sorbents    ☒ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock    ☒ 10 0'Clock    ☒ 2 0'Clock    ☒ 3 0'Clock  
☒ 4 0'Clock    ☒ 5 0'Clock    ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (Specify) ..... NON LEAK .....

iii. Facility

- ☒ Pipeline    ☒ Flow Line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (Specify) NO LEAK

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others (Specify) NO LEAK

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ADIEGBE  
 ii. \_\_\_\_\_  
 iii. \_\_\_\_\_  
 iv. \_\_\_\_\_

### (b) Land (Indicate area in m<sup>2</sup>)

- i. NIL  
 ii. \_\_\_\_\_  
 iii. \_\_\_\_\_  
 iv. \_\_\_\_\_

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken.....NIL.....

10. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

11. Remarks/Recommendation. NAOC SHOULD ALWAYS PROVIDE GAS  
TESTER FOR JUV/ROPAIRS. THEY SHOULD ENHANCE  
SURVILLANCE OF THEIR FACILITY.

12. Time Investigation ended.....1140 HRS......