



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company Nigeria Agip Oil Company
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 19 / 02 / 2023 ii. Date first reported: 19 / 02 / 2023
 - iii. Date of first investigation: 20 / 02 / 2023 v. Spill Incident No: 2023/SAR/NIL/017
 - v. Date of follow-up investigation:
 - vi. Time investigation started: 1402 HRS
 - vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location NAOC 18" KAMBORO TERIDABA BRASS PIPELINE AT KAMB
 - ii. State: BAYELSA STATE L.G.A: SOUTHERN IJAW L.G.A
 - iv. Spill Co-Ordinates: N(m) LAT N04°33'01"
E(m) LON E005°56'02.6"
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify).....
 - iv. Structural Controls in Place
 - ☒ Boom ☒ renches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
 - ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☐ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause of Spill
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify) 3" BALL VALVE WAS INSTALLED FOR ON THEFT ACTIVITIES

6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii. N/A
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

9. Photograph/Map/Chart Ref.

☐ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation..... JIN WAS SUCCEFULL COMPLETED REPAIR
WAS CARRIED - Out SAME DAY

13. Time investigation ended.....