

INC. 2024/LAR/NLI/039



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) GAS

3. Incident Details

- i. Date of Incident: 04/04/2024 ii. Date first reported: 04/04/2024
iii. Date of first investigation: 05/04/2024
iv. Date of follow-up investigation: N/A
v. Time investigation started: 12:38 HRS
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 6" TUOMO-OGBOINBIRI PIPELINE AT LALAGBENE
ii. Position of Spill/Leak: N 05° 00' 51.3" E 005° 55' 29.9"
iii. Spill area:
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify).....

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock 4-7 O'CLOCK

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify).....

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify).....

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify).....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify).....

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☐ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify) N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets ☒ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
...	...	...	...
...	...	...	...
...	...	...	...
...	...	...	...

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
...	...	...	...
...	...	...	...
...	...	...	...
...	...	...	...

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
...	...	...	...
...	...	...	...
...	...	...	...
...	...	...	...

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
...	...	...	...
...	...	...	...
...	...	...	...
...	...	...	...

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

SURVEILLANCE AND SECURITY
WITHIN AND OUTSIDE THE ROW SHOULD
BE ENHANCED.

12. Time Investigation ended.....

14:05 HRS