



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark W. Fraser	
Designation		General Manager Joint Venture Operations	
Phone Number		0817 207 3917	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		016 / 2024	
Section 2 - Location			
State / LGA		Akwa Ibom / Ibeno	
Coordinates of spill		EASTINGS 4Deg 19Min/8Secs N NORTHINGS 8Deg 8Min/59Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		7/4/2024 Time: 14:25 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Unknown: A small sheen was observed and reported approximately 5NM North-West of Ubit facilities by Bristow helicopter crew. Source was unknown as there was no sheen trail observed.	
Status of spill		☐ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify)..... Immediate checks confirmed there were no spills from any MPN facility. No sheen was observed in the area when further search was conducted with surfer boat and helicopter in the early hours of July 5, 2024, indicating the sheen had dispersed naturally and completely	
Product Data	☐ Persistent		☐ Non-Persistent
	Product Name/Type	NA	NA
	SG/API Gravity	NA	NA

	Pour Point	NA	NA
	Wax Content	NA	NA
	Asphaltene	NA	NA
	Sulphur Content	NA	NA
	Viscosity	NA	NA
Oil	Slick Locations(s)	NA	NA

observation	Slick Dimension(s)	NA	NA
	Orientation of slick(s)	NA	NA
	Distribution of oil	NA	NA
	Obvious odour	NA	NA
Oil descriptions	Tarballs (tb)	NA	NA
	Convergence line (co)	NA	NA
	No structure (ns)	NA	NA
	Windrows (wr)	NA	NA
	Streamers (st)	NA	NA
	Patches (pa)	NA	NA
Oil color and appearance	Silver/grey	NA	NA
	Rainbow	NA	NA
	Metallic	NA	NA
	Transitional	NA	NA
	Dark	NA	NA
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☒ Aircraft ☒ Boat ☐ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release		Continuous Release		
			Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.01132 bbls of crude oil based on sheen appearance			
	Coverage	About 100m x 100m of 20% rainbow color and 80% silvery sheen on the sea			
	Direction of travel	Northwest			

Section 5 - Weather

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	Northwest	
Initial Wind Speed	15 knots	
Air Temperature (C or OF)	20	
Visibility Estimate	☐ Good ☒ Fair ☐ Poor	
OCEANOGRAPHIC DATA		
Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐

