



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:
☐ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 07/01/23 ii. Date first reported: 07/01/2023
iii. Date of first investigation: 08/01/23 iv. Spill Incident No: 2023/SAR/NL/002
v. Date of follow-up investigation:
vi. Time investigation started: 10:00 HRS
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 6" AZUZUAMA/IEBIDABA PIPE LINE AT IKEBIRI
ii. State: BATELSA iii. L.G.A: SOUTHERN IJAW
iv. Spill Co-Ordinates: N(m) N 04° 39' 41.4"
E(m) E 005° 55' 09.2"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify) N/A
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Jawsaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify)..... *N/A*

ii. Nature of impact

- ☒ Oil stained vegetation
☒ Oil stained fishing nets
☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others..... *N/A*

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others *N/A*

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☒ Tidal
☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

c) Swamp

- ☐ Tidal
☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

d) River

- ☐ Tidal
☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☐ Boat ☒ Aircraft

12. Remarks/Recommendation..... OPERATOR (AGIP) SHOULD ENSURE
THAT, SURVILLANCE SECURITY ARE PUT IN
PLACE ALWAYS.

13. Time investigation ended..... 11:00 HRS