



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria Unltd.	
Reporting Officer		Mark W. Fraser	
Designation		General Manager Joint Venture Operation	
Phone Number		0817 207 3917	
Email Address		Mark.w.fraser@exxonmobil.com	
Incident Number		017 /2024	
Section 2 - Location			
State / LGA		Inim PP (Enang E Wellhead Platform) / Offshore (OML 67)	
Coordinates of spill		EASTINGS 7Deg 54Min/39.783Secs N NORTHINGS 4Deg 11Min/09.165Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		7/17/2024 Time: 09:30 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☒ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Corrosion: A pin hole leak was observed on Enang-E Wellhead Platform Test Separator desanding line, with splashes of crude beyond the test separator skid resulting in sheen North-East of Enang E.	
Status of spill		☐ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☐ Others (specify).....	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type	NA	NA
	SG/API Gravity	NA	NA
	Pour Point	NA	NA
	Wax Content	NA	NA
	Asphaltene	NA	NA
	Sulphur Content	NA	NA
	Viscosity	NA	NA

Oil	Slick Locations(s)	NA	NA
-----	--------------------	----	----

observation	Slick Dimension(s)	NA	NA
	Orientation of slick(s)	NA	NA
	Distribution of oil	NA	NA
	Obvious odour	NA	NA
Oil descriptions	Tarballs (tb)	NA	NA
	Convergence line (co)	NA	NA
	No structure (ns)	NA	NA
	Windrows (wr)	NA	NA
	Streamers (st)	NA	NA
	Patches (pa)	NA	NA
Oil color and appearance	Silver/grey	NA	NA
	Rainbow	NA	NA
	Metallic	NA	NA
	Transitional	NA	NA
	Dark	NA	NA
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☒ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00296bbl of crude oil based on sheen appearance	
	Coverage	About 400m x 5m of 10% of barely discernible; 35% rainbow colors and 55% silvery sheen on the sea	
	Direction of travel		
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)	Southwest		
Initial Wind Speed	18knots		
Air Temperature (C or OF)	24°C		
Visibility Estimate	☐ Good ☒ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐	Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☐	
Recovery of free phase oil	Yes ☐	No ☐	
Booming	Yes ☐	No ☐	
Wild life rehabilitation	Yes ☐	No ☐	
Dispersant application	Yes ☐	No ☒	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

