

Note: This JIV form is to be completed and signed by all participating parties in the field

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) Pipeline Vandalism

i. Date of Incident: 2-8-2024..... ii. Date first reported: 22-8-2024.....

iii. Date of first investigation: 28-8-2024

iv. Date of follow-up investigation:.....

v. Time investigation started: 11:00 am

vi. Estimated quantity spilled: No oil spill

i. Site/Location: 8" scheduled SD Delivery Pipeline at Idama Com. AK ulatony LGA.

ii. Position of Spill/Leak: Start Point Coord: 256081.5E 508649.5N Rivers State

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify).....

☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) Nine

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (Specify) No oil spill on the vandalised oil pipeline at the time of JVI

☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig☒ Storage Tank ☒ Compressor Plant

☒ Others (Specify)

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (Specify)

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

Some sections of the were vandalized and taken away.