



2024-3578320

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEV. COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 28/08/2024 ii. Date first reported: 28/08/2024  
iii. Date of first investigation: 30-08-2024  
iv. Date of follow-up investigation: N/A  
v. Time investigation started: 14:00 HRS  
vi. Estimated quantity spilled: ELEVEN (11) BBLs

4. Site Details

- i. Site/Location: 14" OKORDIA-RUMUEKPE PIL AT EDEOHA  
ii. Position of Spill/Leak: N 05° 01' 25.33" E 006° 37' 20.72"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline  
☒ Near shore ☒ Offshore ☒ Others (Specify) SEASONAL SWAMP

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) SHUT-IN

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock  
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock ☒ 11 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products  
☒ Others (Specify) .....

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig  
☒ Storage Tank ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident  
☒ Operational Error ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

2024-3578320

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland    ☒ Fish Pond    ☒ Vegetation    ☒ Fishing Net    ☒ Surface water  
☒ Venerable Objects    ☒ Others (Specify) .....

ii. Nature of impact

- ☒ Oil stained vegetation    ☒ Oil stained fishing nets    ☒ Dead floating fishes  
☒ Dead floating crabs    ☒ Withering of vegetation    ☒ Others (Specify) .....

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW    ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. EDEOHA ..... i. 6,600 m<sup>2</sup> .....  
ii. .... ii. ....  
iii. .... iii. ....  
iv. .... iv. ....

(c) Creek/Creek lets    ☒ Tidal    ☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp    ☐ Tidal    ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River    ☐ Tidal    ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water    ☐ Tidal    ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

2024-3578320

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

9. Samples taken... NONE .....

10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation. (U) REPAIR OF AFFECTED FACILITY.

(U) SECURITY TO BE IMPROVED .....

(U) CLEAN-UP OF IMPACTED AREA. .....

12. Time Investigation ended... 15:15 HRS .....

13. Name and Signature of Participants