

14-0689



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: HIERG INTER-GAS

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) _____

3. Incident Details

- i. Date of Incident: 01-09-2024 & Date first reported: 01-09-2024
 ii. Date of first investigation: 01-09-2024
 iii. Date of follow-up investigation: _____
 iv. Time investigation started: 14:00 HRS
 v. Estimated quantity spilled: NO SPILL

4. Site Details BOMASI - IMO RIVER DELTA, LUGA, AKALI

- i. Site Location: 4591 EGN, T7161E
 ii. Position of Spill/Leak: _____
 iii. Spill area: HIA
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) _____
 iv. Structural Controls in Place: N
☐ Boom ☐ Trenches ☐ Bund Wall ☐ Barriers ☐ Others (Specify) _____

5. Circumstances Around Spill Point

- i. Visual observation of Spill Position
☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock
 ii. Type of Oil Contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) NO SPILL
 iii. Facility
☐ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____
 iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) _____
 v. Visible Sign of Third Party Interference
☐ Vessel Wake ☐ Drifted Vessel ☐ Blowing ☐ Other ☐ Acid

A SCUM DRAINER drilled into the scum line at 12 O'clock position by incision pipe (3)

1. Species of Insects

1. Properties Reported by the Insects

- ☐ Terrestrial ☐ Fish-Food ☐ Vegetative ☐ Floating Insects ☐ Surface Water
☐ Possible Climates ☐ Other (Specify) _____

2. Nature of Insects

- ☐ Oil-related vegetation ☐ Oil-related floating water ☐ Short floating water
 (Short floating water) Withering of vegetation Other (Specify) _____

3. Distribution of Insected Area

- ☐ Water Company's Insects (B/C/D) ☐ General Company's Insects (B/C/D)

4. Nature of Insects

(a) Community (Indicate name)

(b) Land (Indicate area in sq)

1. _____ 1. _____
 2. _____ 2. _____
 3. _____ 3. _____
 4. _____ 4. _____

(c) Credit with Insects ☐ Total ☐ New-old

NAME	NUMBER OF INSECTS	LENGTH OF INSECT	WIDTH OF INSECT

(d) Insects ☐ Total ☐ New-old

NAME	NUMBER OF INSECTS	LENGTH OF INSECT	WIDTH OF INSECT

(e) Insects ☐ Total ☐ New-old

NAME	NUMBER OF INSECTS	LENGTH OF INSECT	WIDTH OF INSECT

(f) Insects ☐ Total ☐ New-old

NAME	NUMBER OF INSECTS	LENGTH OF INSECT	WIDTH OF INSECT

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken... Nil

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation...

Hires charges should improve
on the surveillance system of the pipes
to prevent future occurrence.

12. Time Investigation ended... 14:27 HOURS

13. Name and Signature of Participants

❖ NOSDRA