

3722436



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 26-9-24 ii. Date first reported: 26-9-24
iii. Date of first investigation: 26-9-24
iv. Date of follow-up investigation:
v. Time investigation started: 1611 hrs
vi. Estimated quantity spilled: 101 bbls
4. Site Details
i. Site/Location: 24" OBALE-BONNY P/L @ Abura-Udeeme
ii. Position of Spill/Leak: N 4-764895 E 7219902
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)..... Pit
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☐ Fish Pond
 ☒ Vegetation
 ☐ Fishing Net
 ☐ Surface water
☐ Venerable Objects
 ☐ Others (specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☐ Oil stained fishing nets
 ☐ Dead floating fishes
☐ Dead floating crabs
 ☐ Withering of vegetation
 ☐ Others

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i. Norwa - uedeme

ii.

iii.

iv.

b) Land (indicate area in m²)

i. 0.1949

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

① SPDC should recover ^{oil} and
clean-up the ~~area~~ of impact. ② SPDC
should repair the affected facility.