

INCIDENT NUMBER  $\Rightarrow$  2024/LAR/108



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: DANDO OIL COMPANY LIMITED PORT HARCOURT

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 07/10/2024    ii. Date first reported: 07/10/2024  
iii. Date of first investigation: 09/10/2024  
iv. Date of follow-up investigation: N/A  
v. Time investigation started: 5:19 PM  
vi. Estimated quantity spilled: 2.51 BARRELS

4. Site Details

- i. Site/Location: 10" OSHIE - OGONA PIPELINE AT OGONA AWELGA R/S  
ii. Position of Spill/Leak: 05° 06' 52.4" N    006° 34' 07.6" W  
iii. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (Specify) .....  
iv. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund Wall    ☒ Sorbents    ☒ Others (Specify) PLT

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock    ☐ 10 O'Clock    ☐ 2 O'Clock    ☐ 3 O'Clock  
☐ 4 O'Clock    ☐ 5 O'Clock    ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (Specify) .....

iii. Facility

- ☒ Pipeline    ☒ Flow Line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water  
☒ Venerable Objects ☐ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes  
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

9. Samples taken... NIL

10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation... OANDO OIL COMPANY SHOULD  
CLEAN UP THE IMPACTED SITE.

12. Time Investigation ended... 5:45 PM

13. Name and Signature of Participants

❖ NOSDRA