



2024/SAR/GL/071

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: Nigerica Oando oil Company

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify)

3. Incident Details

i. Date of Incident: 12/11/2024 ii. Date first reported: 12/11/2024

iii. Date of first investigation: 12/11/2024

iv. Date of follow-up investigation: ---

v. Time investigation started: 15:55 HRS

vi. Estimated quantity spilled: NIL

4. Site Details

i. Site/Location: 6" TUCOMO/OGBOINBIRI GASLINE AT OGBOINBIRI

ii. Position of Spill/Leak: NO 4° 50' 23.1" E 005° 57' 10.8"

iii. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock

☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock 4 TO 8 O'CLOCK POSITION

ii. Type of Oil Contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (Specify)

iii. Facility

☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant

☒ Others (Specify) GASLINE

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 Dead floating crabs
 Withering of vegetation
 Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation. *Trk COMPLETED*.....

.....

.....

12. Time Investigation ended.....