

STILL PHOTOGRAPHS:



Pic1: Showing one (1no.) 2" valve illegally installed on the pipeline