

INCIDENT NO: 3446733



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: _____
2. Type of Complaint/Accident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify): _____
3. Incident Details
i. Date of Incident: 7/8/24 ii. Date first reported: 7/8/24
iii. Date of first investigation: 6/12/24
iv. Date of follow-up investigation: N/A
v. Time investigation started: 15:00 HRS
vi. Estimated quantity spilled: None 26 ft from time of JIV
4. Site Details
i. Site Location: 36' NKPRRY-OGOLE P/L @ RUMMAY
ii. Position of Spill/Leak: N 4° 54' 47.59" E 7° 0' 25.36" E
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify): _____
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify): None
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify): _____
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify): _____
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify): _____
v. Visible Sign of Third Party Interference
☐ Enclosure Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify): One (1m) 2" valve and one (1m) nipple installed at 12 O'clock position were sighted upon excavation