

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... *None*

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation..... *The company should replace*
the EGA Clamp that failed

12. Time Investigation ended..... *12:45 HRS*

13. Name and Signature of Participants

✦ NOSDRA

h.c.