

JOINT INVESTIGATION VISIT (JIV) FORM

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify)... Asset Damage

i. Date of Incident: 7/12/24 ii. Date first reported: 7/12/24

iii. Date of first investigation: 12/12/24

iv. Date of follow-up investigation:..... 5/1/.....

v. Time investigation started: 14:32 hrs

vi. Estimated quantity spilled:.....No spill.....

i. Site/Location: 12 D9442-EBV04 11200 06000

ii. Position of Spill/Leak: 4° 46' 58.88" N 7° 7' 56.86" E

☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☒ Others (specify)... alone

☐ Boom ☐ Frenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

i. Visual observation of Hole Position

☒ 12 O' Clock
 ☐ 10 O' Clock
 ☐ 2 O' Clock
 ☐ 3 O' Clock
☐ 4 O' Clock
☐ 5 O' Clock
☐ 6 O' Clock

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☒ Others (specify) None

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify) _____☐Hacksaw Marks ☐Drilled Holes ☐Blasting ☐Theft ☐Acid

☐ Hack Saw Marks ☐ Drilled Holes ☐ Blasting ☐ Other ☐ Eaten

☒ Others (specify) 1.5" galvanized pipe attached to
9 1.5" valve installed at 12 o'clock
position on the 12" pipeline

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others... *No impact*

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken

None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

Immediate repair of the
damaged portion of the pipeline.
Security on the ROW should be intensified.

12. Time investigation ended

15:15 HRS

13. Name and Signature of Participants

❖ NOSDRA