



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: Shed Petroleum Development Company

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 11/12/24 ii. Date first reported: 11/12/24
iii. Date of first investigation: 15/12/24
iv. Date of follow-up investigation: N/A
v. Time investigation started: 11:02 HRS
vi. Estimated quantity spilled: 15 bbls

4. Site Details

- i. Site/Location: 20" Kolocreek - Runvappa P/L @ Oday
ii. Position of Spill/Leak: N = 4.93838416 E = 6.50165734

iii. Spill area

- ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (Specify) Seasonal Swamp

iv. Structural Controls in Place

- ☐ Boom ☒ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

2" ball valve connected to a 2" galvanized pipe installed at 12 O'clock position.

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify) *Oil stained soil*

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. *Delau*

(b) Land (Indicate area in m²)

i. *0.084 Ha*

- ii. ii.
 iii. iii.
 iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>
<i>/</i>	<i>/</i>	<i>/</i>	<i>/</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....None.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....Immediate repairs.....and.....

clean-up of the oil impacted area.....
Security should be intensified.....

15.00 HRS