

2024/SAR/NL/139



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: Oando Energy Resources Nigeria Limited

2. Type of Complaint/Incident:

- ☒ Oil Pollution      ☒ Fire/Explosion      ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 21/11/2024      ii. Date first reported: 21/11/2024  
iii. Date of first investigation: 21/11/2024  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 10:35 HRS  
vi. Estimated quantity spilled: 10:35 HRS N/A

4. Site Details

- i. Site/Location: 18" Tebidaba/Brass p/L at nubikiba  
ii. Position of Spill/Leak: N04°29'36.1" E006°04'55.5"

iii. Spill area

- ☒ Land      ☒ Swamp      ☒ Freshwater      ☒ Mangrove      ☒ Coastline  
☒ Near shore      ☒ Offshore      ☒ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom      ☒ Trenches      ☒ Bund Wall      ☒ Sorbents      ☒ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock      ☒ 10 O'Clock      ☒ 2 O'Clock      ☒ 3 O'Clock  
☒ 4 O'Clock      ☒ 5 O'Clock      ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☒ Condensate      ☒ Chemicals      ☒ Refined Products  
☒ Others (Specify) .....

iii. Facility

- ☒ Pipeline      ☒ Flow Line      ☒ Wellhead      ☒ Manifold      ☒ Flow Station      ☒ Rig  
☒ Storage Tank      ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion      ☒ Equipment Failure      ☒ Third Party Interference      ☒ Accident  
☒ Operational Error      ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks      ☒ Drilled Holes      ☒ Blasting      ☒ Theft      ☒ Acid  
☒ Others (Specify) .....



## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland   ☒ Fish Pond   ☒ Vegetation   ☒ Fishing Net   ☒ Surface water  
☒ Venerable Objects   ☒ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation   ☒ Oil stained fishing nets   ☒ Dead floating fishes  
 Dead floating crabs   Withering of vegetation   Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. .... MBIKIBA .....

ii. ....

iii. ....

iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

i. ....

ii. ....

iii. ....

iv. ....

### (c) Creek/Creek lets

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |



8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot                      ☒ Boat                      ☒ Aircraft

11. Remarks/Recommendation.....

OANDO should improve surveillance on its facilities/assets to prevent third party interferences.

12. Time Investigation ended.... 14'57 HRS.....