

18. Sample Collection

19. Photographs:




Fig.1: 7mm tear on the beam box



Fig.2: Well Head

20. Data Collection