



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unlimited	
Reporting Officer		John Itsueli	
Designation		General Manager, Joint Venture Operations	
Phone Number		0817 207 3917	
Email Address		jitsueli@seplatenergy.com	
Incident Number		008 /2025	
Section 2 - Location			
State / LGA		Ubit PP / OML 67	
Coordinates of spill		4° 14.37N / 8° 9.58E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		3/31/2025 Time: 16:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☒ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Unknown: Lifting boat (Boka Southern Ocean) called Ubit Central Control Room (CCR) and reported sheen observed north-side of Ubit GJ platform.	
Status of spill		☐ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☐ Others (specify):	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
Sulphur Content			

	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☒ Boat ☐ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release			
		Per Hour		☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00355bbl of crude oil based on sheen appearance			
	Coverage	About 50m X 10m of 10% rainbow colors, 10% light brown and 80% silvery sheen on the sea.			
	Direction of travel	Southwest			

Section 5 - Weather

METEOROLOGICAL DATA

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	Southwest	
Initial Wind Speed	2knots	
Air Temperature (C or OF)	26°C	
Visibility Estimate	☐ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA		
Water Current Speed	26°C	
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐ No ☒
Recovery of free phase oil	Yes ☐ No ☒
Booming	Yes ☐ No ☒
Wild life rehabilitation	Yes ☐ No ☒
Dispersant application	Yes ☐ No ☒

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

On Site

General Manager, Joint Venture Operations

Agin

John Itsueli

—31AFB6B4837644A...

DATE:

Page 3 of 3