



INCIDENT No: 4537199

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: RENAISSANCE AFRICA ENERGY COMPANY LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) NON LEAK

3. Incident Details

- i. Date of Incident: 1-4-2025    ii. Date first reported: 1-4-2025  
iii. Date of first investigation: 2-4-2025  
iv. Date of follow-up investigation: 1/  
v. Time investigation started: 11:58AM  
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 10' DIEBU - CREEK - NUN RIVER PIPELINE AT OPOROMA  
ii. Position of Spill/Leak: N 4.797054    E 6.107693

iii. Spill area

- ☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom    ☒ Trenches    ☒ Bund Wall    ☒ Sorbents    ☒ Others (Specify) NIL

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock    ☒ 10 O'Clock    ☒ 2 O'Clock    ☒ 3 O'Clock  
☒ 4 O'Clock    ☒ 5 O'Clock    ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (Specify) NIL

iii. Facility

- ☒ Pipeline    ☒ Flow Line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☐ Theft    ☒ Acid  
☐ Others (Specify) 3" NIPPLE CONNECTED TO THE COMPANY 10' PIPE LINE AT 12 O'CLOCK POSITION.

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland   ☐ Fish Pond   ☒ Vegetation   ☒ Fishing Net   ☒ Surface water  
☒ Venerable Objects   ☒ Others (Specify) ..... NIL .....

### ii. Nature of impact

- ☒ Oil stained vegetation   ☒ Oil stained fishing nets   ☒ Dead floating fishes  
 Dead floating crabs   Withering of vegetation   Others (Specify) .... NIL

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. OPOROMA

ii. \_\_\_\_\_

iii. \_\_\_\_\_

iv. \_\_\_\_\_

### (b) Land (Indicate area in m<sup>2</sup>)

i. \_\_\_\_\_

ii. \_\_\_\_\_

iii. \_\_\_\_\_

iv. \_\_\_\_\_

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs   ☒ Video coverage   ☒ Mapping

9. Samples taken.....NIL.....

10. Investigation carried out by

☒ Foot   ☒ Boat   ☒ Aircraft

11. Remarks/Recommendation.....IMMEDIATE REPAIR OF THE FACILITY  
AND THE SURVEILLANCE CONTRACT SHOULD BE  
REVIEWED.....

12. Time Investigation ended.....5:27pm.....