



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
 ☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 30/07/2024
 ii. Date first reported: 30/07/2024
 iii. Date of first investigation: 31/07/2024
 iv. Date of follow-up investigation: N/A
 v. Time investigation started: 13:42 HRS
 vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 6th TUOMO/OSBOINBIRI GASLINE AT AZAMA
 ii. Position of Spill/Leak: N04° 54' 04.1" E005° 56' 36.9"

iii. Spill area

- ☒ Land
 ☒ Swamp
 ☒ Freshwater
 ☒ Mangrove
 ☒ Coastline
☒ Near shore
 ☒ Offshore
 ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom
 ☒ Trenches
 ☒ Bund Wall
 ☒ Sorbents
 ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
 ☒ 10 O'Clock
 ☒ 2 O'Clock
 ☒ 3 O'Clock
☒ 4 O'Clock
 ☒ 5 O'Clock
 ☒ 6 O'Clock
 7 AND 8 O'CLOCK

ii. Type of Oil Contaminant

- ☒ Crude Oil
 ☒ Condensate
 ☒ Chemicals
 ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline
 ☒ Flow Line
 ☒ Wellhead
 ☒ Manifold
 ☒ Flow Station
 ☒ Rig
☒ Storage Tank
 ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion
 ☒ Equipment Failure
 ☒ Third Party Interference
 ☒ Accident
☒ Operational Error
 ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
 ☒ Drilled Holes
 ☒ Blasting
 ☒ Theft
 ☒ Acid

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
Dead floating crabs Withering of vegetation Others (Specify) N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i. /
ii. /
iii. /
iv. /

(b) Land (Indicate area in m²)

- i. /
ii. /
iii. /
iv. /

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

4/15

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation..... NAOC SHOULD INTENSIFY ITS
SURVEILLANCE TO CURB SABOTAGE CASES

12. Time Investigation ended..... 14:00 HRS