



NOSDRA

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC — 1857831

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Incident number: 1857831
ii. Date of Incident: 18-05-2017 iii. Date first reported:
iv. By whom: v. Date reported by company: 31-05-2017
vi. Date of first investigation: 01-06-2017
vii. Date of follow-up investigation:
viii. Time investigation started:
ix. Time investigation ended:
x. Date and time spill was stopped:
xi. Estimated quantity spilled (bbls): (See Appendix C for details) 7.39 BBL
xii. Quantity Recovered (bbls): 4 BBL
xiii. Was repair carried out? ☐ Yes ☐ No

4. Site Details

- i. Facility/Location: 18" ASSG - Rumuekpe (Trunkline) @ Ochi
ii. State/L.G.A.: IMO / OHAJI - GGBEMA
iii. Incident points coordinates: (1)
(2) N 05° 21' 03.4"
(3) E 006° 47' 44.9"
(4)

- iv. Condition of site on arrival: ☒ Oil noticed ☐ No oil noticed
☒ Soil disturbed ☐ Soil not disturbed
☐ Others (Specify)

v. Incident Site Terrain:

- ☒ Land ☐ Swamp ☐ Inland water ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)