

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

RENAISSANCE should review
their Security / Surveillance and further Clean
up the impacted area. Repair the damaged facility
04:35pm This site should be flagged
for further action.

13. Name and Signature of Participants