



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field
1. Company: RENMAISSANCE AFRICA ENERGY COMPANY LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 19 July 2025 ii. Date first reported: 19 July 2025
iii. Date of first investigation: 23 July 2025
iv. Date of follow-up investigation:
v. Time investigation started: 13:04 hrs
vi. Estimated quantity spilled:

4. Site Details

- i. Site/Location:
ii. Position of Spill/Leak: N 5.04343230 E 6.59054813
iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 o'Clock ☐ 10 o'Clock ☐ 2 o'Clock ☐ 3 o'Clock
☐ 4 o'Clock ☐ 5 o'Clock ☐ 6 o'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☐ Others (Specify) N/A

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

6. Impact of Incident

i. Properties Impacted by the Incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
- ☒ Venerable Objects ☒ Others (Specify)

ii. ~~Nature of impact~~

- | | | |
|--|--|--|
| ☒ Oil stained vegetation | ☒ Oil stained fishing nets | ☒ Dead floating fishes |
| Dead floating crabs | Withering of vegetation | Others (Specify) |

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

- | (a) Community (Indicate name) | (b) Land (Indicate area in m ²) |
|-------------------------------|---|
| i. | i. |
| ii. | ii. |
| iii. | iii. |
| iv. | iv. |

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

[illegible]

(d) Swamp

- ☐ Tidal ☐ Non-tidal

[illegible]

(e) River

- ☐ Tidal ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) **Shoreline/water**

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... *ADN*.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

*ADNRA mandated RecL
to carry out repairs immediately.*

12. Time investigation ended.....