



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: **RENAISSANCE AFRICA ENERGY COMPANY**

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: **27-07-2025** ii. Date first reported: **27-07-2025**
 iii. Date of first investigation: **14-08-2025**
 iv. Date of follow-up investigation:
 v. Time investigation started: **10:14 HRS**
 vi. Estimated quantity spilled: **41 BARRELS**

4. Site Details

- i. Site/Location: **G" AJAITON WELL 1L AT AGBIDIAMA**
 ii. Position of Spill/Leak: **N 04° 53' 47.36" E 005° 47' 56.29"**

iii. Spill area

- ☒ Land
 ☒ Swamp
 ☒ Freshwater
 ☒ Mangrove
 ☒ Coastline
☒ Near shore
 ☒ Offshore
 ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom
 ☐ Trenches
 ☐ Bund Wall
 ☐ Sorbents
 ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock
 ☐ 10 0'Clock
 ☐ 2 0'Clock
 ☐ 3 0'Clock
☐ 4 0'Clock
 ☐ 5 0'Clock
 ☐ 6 0'Clock

1-5 o'clock position

ii. Type of Oil Contaminant

- ☒ Crude Oil
 ☒ Condensate
 ☒ Chemicals
 ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline
 ☒ Flow Line
 ☒ Wellhead
 ☒ Manifold
 ☒ Flow Station
 ☒ Rig
☒ Storage Tank
 ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion
 ☒ Equipment Failure
 ☒ Third Party Interference
 ☒ Accident
☒ Operational Error
 ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
 ☒ Drilled Holes
 ☒ Blasting
 ☒ Theft
 ☒ Acid
☒ Others (Specify) **INWARD DENT ON THE FACILITY**

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. AGBI DIKKA

ii.

iii.

iv.

(b) Land (Indicate area in m²)i. 1.19 HA

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK



8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation. (1) CLEAN-UP OF THE IMPACTED AREA
REQUIRED (2) SURVEILLANCE AND SECURITY OF THE
COMPANY'S ASSETS SHOULD BE ENHANCED.

12. Time Investigation ended..... 11:30 HRS