



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unlimited	
Reporting Officer		John Itsueli	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		Jltsueli@seplatenergy.com	
Incident Number		020 / 2025	
Section 2 - Location			
State / LGA		Ubit PP / Mfem DB - OML 68 - Akwa Ibom State	
Coordinates of spill		EASTINGS 06Deg 00Min/Secs N NORTHINGS 8Deg 15Min/22Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		11/11/2025 Time: 10:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES	
		☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline	
		PIPELINE (Specify pipeline diameter)	
		☐ Trunkline ☐ Flowline ☐ Bulkline ☒ Export line ☐ Gas Line	
		STORAGE TANKS	
		☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify).....	
		PRODUCTION FACILITIES	
		☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment failure - Sump tank overflow line releasing oily water onto sea surface flowing northwards from Mfem DB platform.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others: Overflow has stopped and mechanical agitation was carried out around Mfem DB. Sheen dispersed completely same day November 11, 2025.	
Product Data	☐ Persistent		☐ Non-Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
Viscosity			

Oil	Slick Locations(s)		
-----	--------------------	--	--

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.000377 bbls of oily water based on sheen appearance	
	Coverage	About 300m x 2m of 100% silvery sheen on the sea	
	Direction of travel	Northwest	
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)		Northwest	
Initial Wind Speed			
Air Temperature (C or OF)			
Visibility Estimate		☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood		High ☐ Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning		Yes ☒ No ☐	
Recovery of free phase oil		Yes ☐ No ☐	
Booming		Yes ☐ No ☐	
Wild life rehabilitation		Yes ☐ No ☐	
Dispersant application		Yes ☐ No ☐	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling		Surface 2D ☐	Sub-Surface 3D ☐
		Not at this time ☐	

On Site

General Manager, Joint Venture Operations

Agin

John Itzueli

—31AFB6B4837644A.

DATE: 12-Nov-25 | 13:33 WAT

Page 3 of 3