

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

9. Samples taken..... NOT TAKEN .....

10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation.....

RAEC should intensify surveillance  
along the right of way. Clean up impacted area  
and repair the damaged pipeline.

12. Time Investigation ended.....

4:00 pm.

13. Name and Signature of Participant.....