



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization	Mandatory Information Required
Company Name	Seplat Energy Producing Nigeria Unlimited
Reporting Officer	John Itsueli
Designation	General Manager, Joint Venture Operations
Phone Number	+2348172068193
Email Address	Jltsueli@seplatenergy.com
Incident Number	024 / 2025
Section 2 - Location	
State / LGA	Asasa VB Wellhead Platform / OML 67
Coordinates of spill	04Deg 3Min/49secs N 8Deg 02Min/17Secs E
	☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others
Depth of Water (if applicable)	
Section 3 – Spill Details	
Date and Time of spill	2/12/2025 Time: 23:15 hours local time
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline
	PIPELINE (Specify pipeline diameter) ☐ Trunkline ☒ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line
	STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify).....
	PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☒ Others:
Cause of spill	Others: Field Security Vessel reported gas leak on Asasa VB wellhead platform. The gas leak was observed to have small, entrained oil. The leak was traced to a pinhole on the platform riser.
Status of spill	☒ Contained ☐ Not Contained ☐ Unknown
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others: The pinhole was isolated, wells secured and the wellhead platform was shut down. Mechanical agitation was carried out to disperse the sheen. Plans underway to clamp the pin hole.

Product Data	☐ Persistent		☐ Non-Persistent	
	Product Name/Type			
	SG/API Gravity			
	Pour Point			
	Wax Content			
	Asphaltene			
	Sulphur Content			
	Viscosity			
Oil	Slick Locations(s)			
observation	Slick Dimension(s)			
	Orientation of slick(s)			
	Distribution of oil			
	Obvious odour			
Oil descriptions	Tarballs (tb)			
	Convergence line (co)			
	No structure (ns)			
	Windrows (wr)			
	Streamers (st)			
	Patches (pa)			
Oil color and appearance	Silver/grey			
	Rainbow			
	Metallic			
	Transitional			
	Dark			
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☒ Aircraft ☒ Boat ☐ On site ☐ Others.....		
Section 4 – Approximate Duration				
Release Rate	Instantaneous Release		Continuous Release	
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.53 bbl of crude oil based on sheen appearance		
	Coverage	About 1900m x 100m of 10% dull colors, 25% rainbow and 15% silvery sheen on the sea		
	Direction of travel	South West		
Section 5 - Weather				
METEOROLOGICAL DATA			NIMET weather forecast	
Wind Direction (wind direction given from)	South West			
Initial Wind Speed	5 Knots			
Air Temperature (C or OF)				
Visibility Estimate	☐ Good ☐ Fair ☒ Poor			
OCEANOGRAPHIC DATA				
Water Current Speed	0.4 Knots			
Tide Phase: Flood	High ☐	Ebb ☐		
Water Temperature (0C or 0F)	26°C			
High Tide Time				
Source				

Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☐	
Recovery of free phase oil	Yes ☐	No ☐	
Booming	Yes ☐	No ☐	
Wild life rehabilitation	Yes ☐	No ☐	
Dispersant application	Yes ☐	No ☐	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)	
Section 8– Equipment	
On Site	

REPORTING OFFICER: John Itsueli
DESIGNATION: General Manager, Joint Venture Operations

Initial
DO

Signed by:
John Itsueli
31AFB6B4837644A...

SIGNATURE: DATE:

*RBA Report must be submitted within 24 Hours of the Spill Incidence.