



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name	Seplat Energy Producing Nigeria Unlimited		
Reporting Officer	Iyiola Olumide		
Designation	General Manager, Offshore Terminal Operations		
Phone Number	+234 810 282 0349		
Email Address	IOlumide@seplatenergy.com		
Incident Number	006 / 2026		
Section 2 - Location			
State / LGA	BRT Diesel Tank Area / 4° 24'32"N / 7° 08'36"E		
Coordinates of spill	4° 24'32"N / 7° 08'36"E		
	☒ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☐ Offshore ☐ Subsea ☐ Swamp Area ☐ Others:		
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill	4/28/2026 Time: 14:30 hours local time		
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter)		
	☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line		
	STORAGE TANKS ☐ Underground Storage Tanks ☒ Above-Ground Storage tanks ☐ Others (specify).....		
	PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others:		
Cause of spill	Others – During a diesel inter-tank transfer operation using flexible hose, the discharge hose slipped off its fastener at the receiving tank, resulting in a release of diesel (AGO) into the concreted bund wall and a small area of the ground just outside the bundwall.		
Status of spill	☒ Contained ☐ Not Contained ☐ Unknown		
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☒ Bund wall ☐ Sorbent ☐ Others:		
Product Data	☐ Persistent		☐ Non-Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
Oil	Slick Locations(s)		
observation	Slick Dimension(s)		

	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release	Continuous Release	
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.1bbl of discharged AGO (Diesel) made contact with ground surface	
	Coverage		
	Direction of travel		
Section 5 - Weather			
METEOROLOGICAL DATA		NIMET weather forecast	
Wind Direction (wind direction given from)	South West		
Initial Wind Speed	NA		
Air Temperature (C or OF)	NA		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐ Ebb ☐		
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			

Mechanical cleaning	Yes ☐	No ☒
Recovery of free phase oil	Yes ☐	No ☒
Booming	Yes ☐	No ☒
Wild life rehabilitation	Yes ☐	No ☒
Dispersant application	Yes ☐	No ☒
Section 6 – Pre-Entry Activities		
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐ Not at this time ☐

Additional information (please use start date and time)

The AGO pumping operation was immediately halted by the attendant, preventing further release.

Section 8– Equipment

On Site	
---------	--

REPORTING OFFICER: Iyiola Olumide

DESIGNATION: General Manager, Offshore Terminal Operations

Initial

FBU

Signed by:

Iyiola Olumide

83FDB9DCEAE7453...

SIGNATURE:

DATE:

*RBA Report must be submitted within 24 Hours of the Spill Incidence.