



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required
Company Name	Seplat Energy Producing Nigeria Unlimited	
Reporting Officer	Iyiola Olumide	
Designation	General Manager, Offshore Terminal Operations	
Phone Number	0810 282 0349	
Email Address	IOlumide@seplatenergy.com	
Incident Number	007 / 2026	
Section 2 - Location		
State / LGA	Offshore BOP	
Coordinates of spill	EASTINGS 4Deg 13Min/27.3Secs N NORTHINGS 8Deg 03Min/18.2Secs E	
	☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)		
Section 3 – Spill Details		
Date and Time of spill	5/13/2026 Time: 09:30 hours local time	
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☒ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☒ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☒ Others...SPM....	
Cause of spill	Operators conducting routine inspections observed a hydrocarbon sheen around the SPM 2 loading arm. Subsequent inspection identified a crack at the 12 o'clock position of the flange weld within the lower heat-affected zone.	
Status of spill	☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others • Loading arm valves immediately isolated and vessel moved to SPM 3 to line-up for export. • Commenced further inspection of the affected area.	
Product Data	☐ Persistent ☐ Non-Persistent	
	Product Name/Type	
	SG/API Gravity	
	Pour Point	

	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☒ Boat ☐ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release		Continuous Release		
			Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.007075 bbl based on sheen appearance on sea water			
	Coverage	About 150m x 100m of 90% clear water, 5% rainbow color and 5% darkening bands of colors on sea water.			
	Direction of travel				

Section 5 - Weather

METEOROLOGICAL DATA

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	Southwest	
Initial Wind Speed	10	
Air Temperature (C or OF)	28 °C	
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	

Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☐	No ☐

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

Additional information (please use start date and time)


Section 8– Equipment	
On Site	

Initial

OK

Okechukwu Udeji
For
REPORTING OFFICER: Iyiola Olumide.....
DESIGNATION: General Manager, Offshore Terminal Operations
.....

Signed by:

SIGNATURE: 
62A3417B00E1487.....

22-May-26 | 14:52 WAT

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*