CONOG/HSES/SPILL/001

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. **Company:** CONTINENTIAL OIL AND GAS LIMITED (CONOIL)

2. **Type of Complaint/Incident:**

☑ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) .....

3. **Incident Details**

i. Date of Incident: 30/07/2026 ii. Date first reported: 30/07/2026
iii. Date of first investigation: 07/08/2026
iv. Date of follow-up investigation: .....
v. Time investigation started: 1:50PM
vi. Estimated quantity spilled: 20BBLS

4. **Site Details**

i. Site/Location: ANGO FLOW STATION AT KOLUAMA
ii. Position of Spill/Leak: N 04° 30' 26.8" E 005° 44' 22.0"
iii. **Spill area**

☒ Land ☑ Swamp ☒ Freshwater ☑ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify).....

iv. **Structural Controls in Place**

☑ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify).....

5. **Circumstances Around Spill Point**

i. **Visual observation of Hole Position**

☒ 12 0'Clock ☒ 10 0'Clock ☒ 2 0'Clock ☒ 3 0'Clock
☒ 4 0'Clock ☒ 5 0'Clock ☒ 6 0'Clock

ii. **Type of Oil Contaminant**

☑ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify) .....

iii. **Facility**

☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☑ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify) .....

iv. **Cause of Spill**

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☑ Operational Error ☒ Others (Specify) .....

v. **Visible Sign of Third Party Interference**

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify) .....

6. **Impact of Incident**

i. **Properties Impacted by the incident**

☒ Farmland ☒ Fish Pond ☑ Vegetation ☒ Fishing Net ☑ Surface water

☒ Venerable Objects ☒ Others (Specify) .....

ii. **Nature of impact**

☑ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes

✕ Dead floating crabs ✓ Withering of vegetation ✕ Others (Specify) .....

iii. **Delineation of Impacted area**

☑ Within Company's facility/ROW ☑ Outside Company's facility/ROW

7. **Extent of Impact**

(a) **Community** (*Indicate name*)

i. IKOLUAMA

ii. TAMAZO

iii. .....

iv. .....

(b) **Land** (*Indicate area in m^2*)

i. 105,800m^2

ii. .....

iii. .....

iv. .....

(c) **Creek/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) **River** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) **Shoreline/water** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☑ Still photographs ☒ Video coverage ☒ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☑ Foot ☑ Boat ☒ Aircraft

11. **Remarks/Recommendation**. CONOIL SHOULD CLEAN UP THE IMPACTED AREA IMMEDIATELY AND CARRY OUT ROUTINE CHECK FROM TIME TO TIME ON THE KNOCK-OUT DRUM WITHIN THE FLOW STATION. (2) PAYMENT OF COMPENSATION TO AFFECTED COMMUNITIES

12. **Time Investigation ended**.....4:00PM.....