SEEPCO/143/006

NATONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. **Company:** SEEPCO
2. **Type of Complaint/Incident:**
   ☑Oil Pollution ☐Fire/Explosion ☐Drilling Mud/Chemical Pollution
   ☐Others (Specify).....
3. **Incident Details**
   i. Date of Incident: 5/9/2026 ii. Date first reported: 5/9/2026
   iii. Date of first investigation: 7/09/2026
   iv. Date of follow-up investigation: —
   v. Time investigation started: 9:00hrs
   vi. Estimated quantity spilled: < 1bb
4. **Site Details** 12" EN-11 WEST- ENYI MAIN AT OGUU-IKPELE
   i. Site/Location:.....
   ii. Position of Spill/Leak: N5.732970°, E6.648473°
   iii. **Spill area**
   ☐Land ☑Swamp ☐Freshwater ☐Mangrove ☐Coastline
   ☐Near shore ☐Offshore ☐Others (specify).....
   iv. **Structural Controls in Place**
   ☐Boom ☐Trenches ☑Bund wall ☐Sorbents ☐Others (specify).....
5. **Circumstances Around Spill Point**
   i. **Visual observation of Hole Position**
   ☑ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
   ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
   ii. **Type of Oil contaminant**
   ☑Crude Oil ☐Condensate ☐Chemicals ☐Refined Products
   ☐Others (specify) .....
   iii. **Facility**
   ☑Pipeline ☐Flow line ☐Wellhead ☐Manifold ☐Flow Station ☐Rig
   ☐Storage Tank ☐Compressor Plant ☐Others (specify).....
   iv. ***Cause Of Spill***
   ☐Corrosion ☐Equipment Failure ☑Third Party Interference ☐Accident
   ☐Operational Error ☐Others (specify).....
   v. **Visible Sign of Third Party Interference**
   ☐Hacksaw Marks ☐Drilled Holes ☐Blasting ☑Theft ☐Acid
   ☐Others (specify).....

CamScanner

6. **Impact of Incident**

i **Properties impacted by the incident** N/A

☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☐Surface water

☐Venerable Objects ☐Others (specify).....

ii. **Nature of impact**

☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes

☐Dead floating crabs ☐Withering of vegetation ☐Others.....

iii. **Delineation of impacted area**

☐Within Company's facility/ROW ☐Outside Company's facility/ROW

7. **Extent of Impact**

a) **Community** (*indicate name*)

i. Ogulu-Ipete

ii. .....

iii. .....

iv. .....

b) Land (*indicate area in m^2*)

i. 5.6

ii. .....

iii. .....

iv. .....

b) **Creeks/Creek lets** ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp** ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River** ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

CamScanner



CamScanner