



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unlimited	
Reporting Officer		Iyiola Olumide	
Designation		General Manager, Offshore Technical Operations	
Phone Number		+234 810 282 0349	
Email Address		IOlumide@seplatenergy.com	
Incident Number		009 / 2026	
Section 2 - Location			
State / LGA		Around BOP	
Coordinates of spill			
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others:	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		7/8/2026 Time: 10:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others:	
Cause of spill		Mystery Sheen – During area checks the BOP team sighted a stretch of oil sheen passing by the platform. Sheen was observed to be located between Edop PP and Inim PP and heading northwards.	
Status of spill		☐ Contained ☐ Not Contained ☒ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others: Sheen dispersed naturally	
Product Data	☐ Persistent		☐ Non-Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		
observation	Slick Dimension(s)		

	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release	Continuous Release	
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.000503bbl of oily material based on sheen appearance	
	Coverage	About 100m x 50m of 96% clear water; 3% rainbow colors and 1% silvery sheen on the sea	
	Direction of travel	Northwards	
Section 5 - Weather			
METEOROLOGICAL DATA		NIMET weather forecast	
Wind Direction (wind direction given from)	North East		
Initial Wind Speed	NA		
Air Temperature (C or OF)	NA		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐ Ebb ☐		
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☒	
Recovery of free phase oil	Yes ☐	No ☒	
Booming	Yes ☐	No ☒	
Wild life rehabilitation	Yes ☐	No ☒	
Dispersant application	Yes ☐	No ☒	
Section 6 – Pre-Entry Activities			

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: Iyiola Olumide
DESIGNATION: General Manager, Offshore Terminal Operations

Initial
DO

Signed by:
Iyiola Olumide
SIGNATURE: 83FDB9DDCEAE7453.....

DATE: 09-Jul-26 | 10:03 WAT

*RBA Report must be submitted within 24 Hours of the Spill Incidence.